

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
IOWA,
7-WATLO,
3-

Waterloo Water Works, Well House 4
(Cedar Park Restroom)
Fairview and Lafayette Avenues
Waterloo
Black Hawk County
Iowa

HABS No. IA-125

Sarah Dennett and Hans Muessig, Photographers 1978

IA-125-1 EXTERIOR, GENERAL VIEW, SOUTH AND EAST SIDES

IA-125-2 EXTERIOR, WEST SIDE

IA-125-3 EXTERIOR, EAST AND NORTH SIDE

IA-125-4 EXTERIOR, SOUTH SIDE

IA-125-5 EXTERIOR, SOUTH AND EAST SIDES

IA-125-6 EXTERIOR, DETAIL, NORTH SIDE, BRICKWORK AND EAVES

IA-125-7 EXTERIOR, DETAIL, SOUTH SIDE, METAL DOORS

IA-125-8 INTERIOR, SOUTH SIDE, METAL DOORS

IA-125-9 INTERIOR, FLOOR HATCH TO BASEMENT